# Mounting aid
MH 01-M18

- Suitable for M18 sensors
- Simple and fast mounting

Mounting brackets for sensors

Dimensions

## Technical Data

| General specifications	
Inside diameter	18 mm
Mechanical specifications	
Material	Clamping cylinder: Diecast zinc Support bracket: Steel

Refer to "General Notes Relating to Pepperl+Fuchs Product Information".

Pepperl+Fuchs Group
www.pepperl-fuchs.com

USA: +1 330 486 0001
fa-info@us.pepperl-fuchs.com

Germany: +49 621 776 1111
fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091
fa-info@sg.pepperl-fuchs.com

PEPPERL+FUCHS

1

Mounting

1

(a)

(c)

(b)

Fasten the two parts of the mounting clamp (a) loosely by means of the screw (b) and the nut (c) supplied.

2

(d)

(b)

Attach the mounting bracket (d) and then tighten the screw (b) in such a way that the bracket can still be turned.

3

(b)

Tighten the screw fully after the sensor has been mounted and aligned.

Refer to "General Notes Relating to Pepperl+Fuchs Product Information".

Pepperl+Fuchs Group
www.pepperl-fuchs.com

USA: +1 330 486 0001
fa-info@us.pepperl-fuchs.com

Germany: +49 621 776 1111
fa-info@de.pepperl-fuchs.com

Singapore: +65 6779 9091
fa-info@sg.pepperl-fuchs.com

PEPPERL+FUCHS

2